

On August 17, 2023, the Calaveras County Environmental Health Department (EHD), received your complaint for 1001 Lilac Park Drive in Arnold California, which stated the following:

"pit well is on premises adjacent to pool under shed & at bottom of step slope, proper distance from homeowner septic – by design. Septic is downslope from pit well – somewhere. Investigate & cap & destroy due to possible groundwater contamination vector. Unclear if in use today."

On August 18, 2023, EHD staff conducted a complaint-based inspection to investigate the alleged site conditions. Upon thorough investigation of the area including the shed in question, which is located directly outside the swimming pool fence/enclosure, a "pit well" was not observed by EHD staff. Long-time Lilac Park resident, who accompanied EHD staff stated that no wells were ever drilled on the alleged site/location at the HOA property.

Thank you for bringing this matter to our attention.

Mark Landau

Registered Environmental Health Specialist
Calaveras County Environmental Health Department
891 Mountain Ranch Road
San Andreas, CA 95249
209.754.6745 direct
209.754.6399 main
209.754.6722 fax
mlandau@calaverascounty.gov